CERTIFICATE OF STRUCTURAL SOUNDNESS

Name OF the Institution

Seethamahalakshmi D.A.V. Public School Annavaram (Village), Palakonda (Post) – 532 440 Srikakulam (Dist.), A.P.

Date of Inspection

16-02.2021.

The existed building is located at Annavaram (Village), Palakonda (Mandalam), Srikakulam (Dist.). The existed building consists of Ground Floor & 1st Floor, In Ground Floor 14 Rooms and 2 Toilet Rooms (Boys - 1 & Girls - 1), 1st Floor 15 Rooms and 2 Toilet Rooms (Boys - 1 & Girls - 1) and 2nd Floor 1 Room are existed.

The building is structurally sound enough with proper ventilation to run the School.

Signatt

Dy. Executive Engineer PIU, Palakonda

Executive Engineer P.R. Division, Palakonda

No Kin

PRINCIPAL SEETHAMAHALAKSHMM D.A.V. PUBLIC SCHOOL ANNAVARAM, PALAKONDA Srikakulam (Dist.) - 532440