**APPNENDIX - XI** 

## BUILDING SAFETY CERTIFICATE

797/2023-24/PWD No.

Dated: 27-07-2023

Certified that the existing building TRAN MPS KUDKAT, PENDRA (name of the
building or premises) at KNOKALI. PERVISIL
(address) comprised of
(upper floors) Owned/occupies
DAY MPS KUDKAI PENDRA complied with the
(name of the institution) have
Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of $P(M, D)$ (Name of Department/ Govt.)
the officers concerned of
$h \Delta u \Delta = h = 0 = 0 + 0 + 0 + 0 + 0 + 0 + 0 + 0 + 0$
that the human bat
upto classes <u>LRG1</u> (X/XII) with clicct inclusion of the specific <u>30</u>
conditions as appended.

2. reference to location, altitude, intensity of wind, flood 3. J. Dre Safety inspection/ report should be done by 4. agency / seperately. at 27-7-23 by Isqued

\* Strike out whichever is not applicable.

Divisional Officer Signature with Seal Public Works Department Marwahi Sub Division Marwahi Name : 5. K. UKT

Designation :  $\underline{A \cdot E}$ .

Name & Address of Department/ Office: Ph

(Assistant Engineer & above officer of concerned Govt. Department only) GPM

Note: This certificate should be signed / issued by Assistant Engineer & above officer of

concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.