कार्यालय, अनुविभागीय अधिकारी, लोक निर्माण विभाग उपसंभाग कवर्धा जिला कबीरधाम (छ.ग.)

ज्ञापन क. / शि. / 2025

कवर्धा दिनांक

प्रति,

कार्यपालन अभियंता लोक निर्माण विभाग कवर्धा संभाग कवर्धा

विषयः– भवन सुदृढ़ता प्रमाण पत्र प्रदाय करने बाबत्। संदर्भः– प्राचार्य डी.ए.वी. मुख्यमंत्री पब्लिक स्कूल धरमपुरा का पत्र क्र./Ref:PRINCIPAL DAVMPS/DHARAMPURA/2022-23/130 दिनांक 28/01/2025

उपरोक्त विषयांतर्गत लेख है कि संदर्भित पत्र के द्वारा विषयांकित निर्मित भवन का सुदृढ़ता प्रमाण पत्र प्रदाय करने हेतु आवेदन इस कार्यालय में प्रस्तुत किया गया था। उक्त भवन का आज दिनांक 12/02/2025 को उपअभियंता श्रीमती दुर्गाराय द्वारा निरीक्षण किया गया निरीक्षण उपरान्त डी.ए.वी. मुख्यमंत्री पब्लिक स्कूल धरमपुरा जिस भवन में संचालित है वह भवन आवश्यक मरम्मत किये जाने की शर्त पर भवन सुरक्षा प्रमाण पत्र प्रदाय किया जा सकता है।

-----00----

अग्रिम एवं आवश्यक कार्यवाही हेतु आपकी ओर सम्प्रेषित है।

सहपत्रः- प्रमाण पत्र।

पृ.क. / 499 / शि. / 2025

प्रतिलिपीः-• 1. प्राचार्य डी.ए.वी. मुख्यमंत्री पदिलक स्कूल धरमपुरा जिला कबीरधाम की ओर सूचनार्थ प्रेषित। 2. श्रीमती दुर्गाराय उपअभियंता मुख्यालय उपखण्ड क्रमांक 01 कवर्घा की ओर सूचनार्थ अग्रेषित।

सहपन्नः - सूर्या प्रमाग पत्र

d:\sdo pwd\rai mem\letter.docx, 261

अनुविभागीय अधिकारी लोक निर्माण विभाग उपसमाग कवधो

अन्विभागीय अधिकारी

लोक निर्माण विभाग उपरांभाग कवर्धा



कवर्धा दिनाक 12 02 2025

भवन सुरक्षा प्रमाण पत्र

प्राचार्य डी.ए.वी. मुख्यमंत्री पब्लिक स्कूल धरमपुरा वि.ख. कवर्धा जिला कबीरधाम द्वारा प्रस्तुत आवेदन दिनांक 28/01/2025 के आधार पर किया गया निरीक्षण दिनांक 12/02/2025 के आधार पर यह प्रमाणित किया जाता है कि डी.ए.वी. मुख्यमंत्री पब्लिक रकूल धरमपुरा वि.ख. कवर्धा जिस भवन में संचालित है वह भवन आवश्यक मरम्मत किये जाने की शर्त पर ही वर्तमान में स्कूल संचालन हेतु सुदृढ़ एवं सुरक्षित प्रतीत हो रहा है।

यह प्रमाण पत्र जारी होने की तिथि से 01 वर्ष के लिए मान्य होगा।

अनुविभागी/य अधिकारी, लोक निर्माण विभाग उपसंगाग कवर्घा

ত্ত্বপঞ্জা

लोक निर्माण विभाग उपसंभाग कवर्धा



APPNENDIX - XI

BUILDING SAFETY CERTIFICATE

No. 510

02 2025

Certified that the existing building DAV MPS Dharampura (name of the building or premises) at Dharampura, block-Kawardha, Kabirdham (C.G.) (address) comprised of basement(s) and Ground floor (upper floors) owned/occupied by DAV Mukhya Mantri Public School Dharampura (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Work Departmentame of Department Govt) on. 12/02/2025...(date inspection) in of the presence of SUB Divisinal Officer (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy 0.3..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. 2. 3.

4.

Issued on 12/02/2025 at Kawardha by

* Strike out whichever is not applicable.

Signature with Seal :
Name: Lavanya Pup Pargaing
Designation: Actic rat English
Name & Address of Department/ Office: Sub. Divisional Office:
P.W.D.Sub-Dn, Kawardha
(Assistant Engineer & above officer of concerned Govt. Department only)

<u>Note:</u> This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

