APPENDIX – XIII

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

Dated: 26.04.2024

It is certified that an inspection team headed by B. P. chatuwed ani (Assistant-Engineer (Name of Officers with designation) from Public Health Engineering Separtment Korb (Name Of Department/ office) inspected the DAV Mukhya manini Publishe & Address Kharmon of the school)on.26:04:203 (date of Inspection) and found that the M public CChON Khorma Offichool) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt. Signature with Seal..... सहायक अभियता Name: सिक स्वास्थिय यात्रिक Vedani Name & Address of the Office/ Department: Public Health Eng. Department Sub-Dix. - Korba

Principal DAV Mukhyamantri public school Kharmora (Korba) (Name & Address of the Institution)

No. 572

he filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated Parized version in English be uploaded along with the original vernacular certificate as a single PDF.