APPNENDIX - XIII PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE 29/05/23 No. 674 Dated:

It is certified that an inspection team headed by Hash Kabin
(Name of Officers with designation) from Public Health Engineering Department
(Name of Department/ Office) inspected the D.D.Y. Muking Dantay Public School
(Name & Address of the school) on $29/05/2023$ and found that the
D.W. Muy Wa manter public school, saily has safe drinking water
facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation
condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of01	Lycars (one y can)
	Signature with Seal: Assistence Sub Dr.
	Name : Hays bikATGAbisy
	Designation : Assistant Engineen
	Name & Address of the Office / Department : Public
	Health Engineering department
	V V ·

TO, Principal D.D.V. Muyhysmantin Public school, Saila, Korba (C.G.)