BUILDING SAFETY CERTIFICATE

NO. 789

DATE-09 03 2022

Certified that the DAV mukhyamantri public school at Honawandi (Vishrampuri) District- kondagaon

1. R.C.C. inclined roof are in good condition.

- 2. Flooring is in good condition.
- 3. Toilet is in good condition.

So certified the building is safe in all Purpose.

Chief Executive Officer Janpad Panchayat Bederajpur Vishrampuri Distt. Kondageon